


1603 South 14<sup>th</sup> Street • Princeton, MN 55371 Phone: 763-389-9475 • Fax: 763-389-9757 Website: www.erdmanautomation.com E-mail: <u>eac@erdmanautomation.com</u>

## Suggested Initial & Preventative Maintenance Kawi Shaft



Sealant will work around the gear in this area



This is where the sealant ends up lubricates thrust plate. Grease / Vaseline could be put here during reassembly to prevent start up squeaking.